Oil Field Environmental Incident Summary

Responsible Party: OXY USA INC. **Well Operator:** OXY USA INC.

Well Name: DELVIN DUKART 6-30-31H-143-95

Field Name: MANNING Well File #: 28730

Date Incident:2/10/2015Time Incident:17:30Facility ID Number:County:DUNNTwp:143Rng:95Sec:19Qtr:

Location Description:

Submitted By: Dustin Tescher Received By:

Contact Person: Dustin Tescher

5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units
2 Barrels 2 barrels

Brine Other

Oil

Description of Other Released Contaminant:

Inspected: Written Report Received: 7/9/2015 Clean Up Concluded: 2/3/2015

Risk Evaluation:

NA

Areal Extent:

Potential Environmental Impacts:

NA

Action Taken or Planned:

Valve was closed to prevent further releases.

Wastes Disposal Location: TBD

Agencies Involved:

Updates

Date: 2/11/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.